



## MOUNTING SUGGESTIONS

### Triumph Thunderbird 2010-2018 One-piece Seat

**Hardware:** Stock rear screw

**Tools needed:** 5mm Allen wrench  
8mm wrench

#### Removal of stock seat:

1. Remove the 6mm rear screw from the fender with a 5mm Allen wrench.
2. Slide the passenger seat back, out of the fender bracket, and then up and off the fender.
3. Locate and remove the two solo seat side mounting bolts (slightly forward of the shocks) with a 5mm Allen wrench. These will not be needed to install your new Mustang seat.
4. Lift the rear of the solo up, and then back to remove from the motorcycle.



## Installation of Mustang seat:

1. Remove the seat bracket from the fender with an 8mm wrench. Replace the bolts and washers into the fender and tighten securely.
2. Place the seat onto the frame and slide it forward, engaging the nose bracket into the receiver under the gas tank.
3. Install the stock 6mm rear screw through the rear seat bracket and into the fender. Tighten securely with a 5mm Allen wrench.




**Enjoy the comfort and custom look of your new Mustang seat!**



These steps are guidelines to help you install your new Mustang product. If you need further assistance, please call us at 800-243-1392 or 413-668-1100, Monday through Friday 8:30 - 5:00 Eastern or send an e-mail to [tech@mustangseats.com](mailto:tech@mustangseats.com) or visit our website at [www.mustangseats.com](http://www.mustangseats.com).

For care and maintenance of our seats, please go to our website under "Support".

Refers to part numbers: 76837, 76838



Products made by Mustang Motorcycle Products, LLC are warranted for one year against defects in material and workmanship. Mustang must first be notified of any apparent defect. A return authorization will be issued. Carefully pack the product and return prepaid. Upon receipt, Mustang will make a fair, prompt decision regarding repair or replacement.

Incidental and consequential damages arising from or in connection with the installation or use of a Mustang product are not covered by this warranty. An original purchase receipt must be provided to obtain a warranty repair or replacement.